

	SONARtrac® Technical Bulletin	
	Subject: Transmitter Sensor Test Routine	TB003
		Priority: 3
		Date: 16 Jul 04
		Rev: 01

One of the diagnostic features within the SONARtrac® flow monitoring system is the 'Sensor Test' selection found in the 'Diagnostics' menu.

Inconsistent or incorrect test results sometime occur when using this test in software versions 01.06.06 and earlier. Therefore, this test should not be used.

Software release 02.XX.XX, due to be released soon, has a much more robust version of the sensor test routine.

Priority Code:			
1	Safety issue or system will not function	2	Intermittent problem causing system crash
3	Erratic data/readings	4	Added product feature
5	Product enhancement		

CiDRA Corporation
Tel. 203-265-0035

50 Barnes Park North
Fax. 203-294-4211

Wallingford, CT 06492
www.cidra.com

	SONARtrac® Technical Bulletin	
	Subject: Transmitter Sensor Test Routine	TB003
		Priority: 3
		Date: 16 Jul 04
		Rev: 01

Document Change History

Date	Revision	Changed By	Description of Change
7/19/04	01	R. Markoja	Initial Release

Priority Code:			
1	Safety issue or system will not function	2	Intermittent problem causing system crash
3	Erratic data/readings	4	Added product feature
5	Product enhancement		

CiDRA Corporation
Tel. 203-265-0035

50 Barnes Park North
Fax. 203-294-4211

Wallingford, CT 06492
www.cidra.com