

	SONARtrac[®] Technical Bulletin		
	Subject: Fieldbus Foundation™ Software Bug	TB017	Rev: 2
		Priority: 1	
			Page 1 of 2

Problem:

An incorrect entry in the software for the Comm Class for the CFF file was made by Softing, our vendor for Fieldbus Foundation. This problem affects ABB System Hosts. This particular file was part of Firmware Release 04.01.16 and 04.02.26.

Resolution:

If you are using Fieldbus Foundation communications protocol and your customer has an ABB System Host this can be corrected by:

1. Firmware Release 04.02.27 and above contains a corrected version of the CFF file. (It is not necessary to install the new Firmware.) Download and install the latest .CFF file.
2. This software is also available on the web site at <http://www.cidra.com/downloads.asp> and go to Category 'Software' and then 'Select'.

Note: The Fieldbus Foundation web site may not have the latest files available for download. It is always advisable to go to the CiDRA web site.

Contact Technical Support with any questions

Priority Code:			
1	Safety issue or system will not function	2	Intermittent problem causing system crash
3	Erratic data/readings	4	Added product feature
5	Product enhancement		

	SONARtrac[®] Technical Bulletin		
	Subject: Fieldbus Foundation™ Software Bug	TB017	Rev: 2
		Priority: 1	
			Page 2 of 2

Document Change History

Date	Revision	Changed By	ECO #	Description of Change
29Apr08	1	Markoja	E08-0038	Initial Release
15Oct09	2	Markoja	E09-0069	Revise location of file on web site and update graphics

Priority Code:			
1	Safety issue or system will not function	2	Intermittent problem causing system crash
3	Erratic data/readings	4	Added product feature
5	Product enhancement		

CiDRA Corporate Services
Tel. 203-265-0035

50 Barnes Park North
Fax. 203-294-4211

Wallingford, CT 06492
www.cidra.com