

	SONARtrac[®] Technical Note	
	TN0011	
	Subject: SONARtrac Storage and Preservation Instructions	
		Date: 27Jan10
		Revision 03
		Page 1 of 2

Question:

Please provide storage / preservation instructions for SONARtrac Monitoring Systems.

Answer:

The following preservation procedures should be used when storing and shipping SONARtrac Monitoring Systems:

Condition	Minimum / Maximum Value
Temperature - Transmitter	-22°F to +176°F (-30°C to +80°C)
Temperature - Sensor Head	-40°F to +185°F (-40°C to +85°C)
Temperature - Standard Transmitter to Sensor Head Cable	-4°F to +221°F (-20°C to +105°C)
Temperature - Armored Transmitter to Sensor Head Cable	-40°F to +221°F (-40°C to +105°C)
Pressure - Storage / Shipping	No Requirement
Humidity	0 to 100% Non-Condensing
Storage Information	Store in Dry Indoor or Enclosed Area Do Not Expose to Moisture Do Not Store Boxes Directly on Floor Do Not Stack Pallets or Skids on Top of Each Other Keep Materials In Original Packaging Until Installation No Special Preservation is Required for Short or Long Term Storage

Contact CiDRA Corporate Services Customer Support if additional information is required.

CiDRA Corporate Services	50 Barnes Park North	Wallingford, CT 06492
Tel. 203-265-0035	Fax. 203-294-4211	www.cidra.com

	SONARtrac[®] Technical Note		
	TN0011		Date: 27Jan10
	Subject: SONARtrac Storage and Preservation Instructions		Revision 03
			Page 2 of 2

Revision History

Rev	Date	Changed By	Approved By	Change Description
01	8Feb08	Markoja		Initial Release
02	29Jul08	B. Markoja	B. Markoja	Revision #2
03	27Jan10	B. Markoja	B. Markoja	Added additional storage information

CiDRA Corporate Services	50 Barnes Park North	Wallingford, CT 06492
Tel. 203-265-0035	Fax. 203-294-4211	www.cidra.com