

	<b>SONARtrac<sup>®</sup> Technical Bulletin</b>		
	Subject: Gauge Block and Screw Size Table	TB022	Rev: 01
		Priority: 5	
			Page 1 of 2

**Reference: P/N 20822-01 Installation Manual, Chapter 5 Sensor Installation P/N 20832-01 Section 5.6.1, Table 4 Gauge Block and Screw Size**

The referenced table lists the sensor band part number, spacer gauge tool, sensor band screw hex wrench size and band attachment rail size. This table has been revised to include gauges and sensors not currently listed in the manual and additional reference information.

When P/N 20822-01 Installation Manual is next revised the following table will be incorporated into Chapter 5.

Gap Tool Part Number	Sensor Band Part Number(s)	Gap Size (inch) ±0.001	# Belleville Washers	Socket Head Screw Size / Hex Size (inch)
20143-01	20380, 20644, 20673, 20745, 20781	0.165	10	#6 screw 7/64 hex size
20143-02	20409 Obsolete	0.236	14	#6 screw 7/64 hex size
20143-03	20669-02 thru 20669-04	0.496	30	#6 screw 7/64 hex size
20143-04	20686, 20690, 21059	0.293	14	#10 screw 5/32 hex size
20143-05	Special applications	0.209	10	#10 screw 5/32 hex size
20143-08	20991, 20669-01, 20669-16	0.627	30	#10 screw 5/32 hex size

*Table 4 Gauge Block and Screw Size*

Please contact Customer Support with any questions.

Priority Code:			
1	Safety issue or system will not function	2	Intermittent problem causing system crash
3	Erratic data/readings	4	Added product feature
5	Product enhancement		

CiDRA Corporate Services  
Tel. 203-265-0035

50 Barnes Park North  
Fax. 203-294-4211

Wallingford, CT 06492  
www.cidra.com

	<b>SONARtrac<sup>®</sup> Technical Bulletin</b>	
	Subject: Gauge Block and Screw Size Table	TB022   Rev: 01
		Priority: 5
Page 2 of 2		

### Document Change History

Date	Revision	Changed By	ECO #	Description of Change
7/29/09	01	B. Markoja	E09-0051	Initial Release

<b>Priority Code:</b>			
1	Safety issue or system will not function	2	Intermittent problem causing system crash
3	Erratic data/readings	4	Added product feature
5	Product enhancement		

CiDRA Corporate Services  
Tel. 203-265-0035

50 Barnes Park North  
Fax. 203-294-4211

Wallingford, CT 06492  
www.cidra.com